



**EXAMPLE OF POND
 OUTLET
 CONTROL MANHOLE**

FRANKLIN
 ENGINEERING DEPT.

FIGURE 17